

连杆锁

[illegible]

Technical drawing of a stepped shaft. The shaft has a total length of 100 units. It consists of two main sections: a left section with a diameter of 25 units and a length of 50 units, and a right section with a diameter of 50 units and a length of 50 units. The transition between the two sections is a smooth fillet. The drawing includes dimension lines and labels for the diameters (25 and 50) and the lengths (50 and 50).

[illegible]

见角标准：第一视

EX
Example
使用示例

 请按图示订货

型号		L长度	X长度	h
代码	连杆	连杆1	连杆2	
XAU45	W(无)	—	—	—
	A(A型)	100~1500	100~1500	32
	B(B型)			38

XAU45—W
XAU45—A—L100—X100—h32

数量	1~9	10~
价格	100%	另行报价

二、

