## 转轴


## ≺ 一端内螺纹型・标准型

一端台阶型









D·P	g6	h7	h9	
3	-0.002	0	0	
	-0.008	-0.010	-0.025	
3.1~6	-0.004	0	0	
	-0.012	-0.012	-0.030	
6.1~10	-0.005	0	0	
	-0.014	-0.015	-0.036	
10.1~18	-0.006	0	0	
	-0.017	-0.018	-0.043	
18.1~30	-0.007	0	0	
	-0.020	-0.021	-0.052	
30.1~50	-0.009	0	0	
	-0.025	-0.025	-0.062	

视角标准:第一视角

① 圆度·直线度·垂直度·同轴度,	请参阅转轴产品简介。
-------------------	------------

型号		最小单	望位0.1	最小单位1	М					
代码	D <sub>g6</sub>	L	Е	Р	IVI					
	6	18.0~300.0		5	3					
	8	18.0~400.0			3 4 5					
	10	18.0~500.0		M3~M8时	4 5 6					
	12	20.0~600.0		M+2≤P <d< td=""><td>5 6 8</td></d<>	5 6 8					
	13	20.0~000.0		WITZ P U	5 6 8					
	15	20.0~700.0		M10~M16时 M+2《P <d M20·24时 M+2《P<d< td=""><td>5 6 8 10</td></d<></d 	5 6 8 10					
MBJ01	16		1≤E≤P×6		5 6 8 10					
MBJ02	17				5 6 8 10 12					
MBJ16					5 6 8 10 12					
MID5 10	20	25.0~800.0			5 6 8 10 12					
	22				5 6 8 10 12 16					
	25			1400E4	5 6 8 10 12 16					
	30			M30时	8 10 12 16 20					
	35			M+2≤P <d< td=""><td>8 10 12 16 20 24</td></d<>	8 10 12 16 20 24					
	40	35.0~800.0			12 16 20 24 30					
	50				16 20 24 30					

n/	<del>-</del>														
型号		最小单位0.1		最小单位1	М										
代码	D <sub>h</sub> 7	L	E	Р	IVI										
	6	18.0~300.0		5	3										
	8	18.0~400.0		M3~M8时	3	4	5								
	10	18.0~500.0		M+2≤P <d< td=""><td></td><td>4</td><td>5</td><td>6</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></d<>		4	5	6							
	12	20.0~600.0					5	6	8						
MBJ41	15	20.0~700.0		M10~M16时			5	6	8	10					
MBJ42	20		1≤E≤P×6	M+2≤P <d< td=""><td></td><td></td><td>5</td><td>6</td><td>8</td><td>10</td><td>12</td><td></td><td></td><td></td><td></td></d<>			5	6	8	10	12				
11111111111	25	25.0~800.0		M20·24时			5	6	8	10	12	16			
	30			M+2≤P <d< td=""><td></td><td></td><td></td><td></td><td>8</td><td>10</td><td>12</td><td>16</td><td>20</td><td></td><td></td></d<>					8	10	12	16	20		
	35			M30时					8	10	12	16	20	24	
	40	35.0~800.0		-							12	16	20	24	30
	50			M+2≤P <d< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>16</td><td>20</td><td>24</td><td>30</td></d<>								16	20	24	30

O h9					
型号		最小单位0.1		最小单位1	M
代码 Dh9		Ш	Е	Р	IVI
	6	18.0~300.0		5	3
MD IC4	8	18.0~400.0		M3~M8时	3 4 5
MBJ61	10	18.0~500.0			4 3 0
MBJ62 MBJ66	12	20.0~600.0		M+2≤P <d< td=""><td>5 6 8</td></d<>	5 6 8
MBJ81	15	20.0~700.0	1≤E≤P×6	M10~M16时	5 6 8 10
MBJ82	20			M+2≤P <d< td=""><td>5 6 8 10 12</td></d<>	5 6 8 10 12
MBJ86	25	25.0~800.0		M20-24B寸	5 6 8 10 12 16
MIDJOO	30			M+2≤P <d< td=""><td>8 10 12 16 20</td></d<>	8 10 12 16 20
	35	35.0~800.0		MITZ < F < D	8 10 12 16 20 24

ſ	可选加工	#							
	代码	技术说明							
j)	LC	变更L尺寸公差	选型方法] LC ①L<400变更为L±0.05 L≥400变更为L±0.1						
	LA() LB()	増加1处平面LA()    (1)	选型方法 LA10-G3 选型方法 LB10-J3-Y10-X3 ①最小单位1 ①指定G·J·X时,须为50以下						
	KB() KC()	増加1处键槽KB()	选型方法 KB50-S10 选型方法 KC50-C8-F40-T10 显示单位1 指定S-T-C时,须为100以下 需要处键槽时,请同时选择KB与KC U键槽详情见转轴产品简介。						
	KD()	増加开口凸轮用槽	<u>洗型方法</u> KD10  ① 最小单位1  10 最小単位1  10 8 7 4 10 8 5 12 10 5						
ţħ.	MA() MB()	増加挡圏槽(附帯挡圏)	选型方法 MA10 — MB10 ① 最小单位1 ② MA(MB)=4~L/2 ② 挡圈槽尺寸见转轴产品简介。						



	型毛	7		_			
	代码	D	L	E	P	IVI	, I
•	MBJ01	(8)	18~400	_	M3~M8时	3 4 5	١.
	MBJ01	10	18~500	1≤€ <b>⊙</b> ×6	M+25P <d< td=""><td>4 5 6</td><td>Ņ,</td></d<>	4 5 6	Ņ,









请按图示订货

MBJ02-D8-L150-E20-P5-M3
○ 可洗加丁

O POWAL										
型된	3		Е	D	NA.	可选加工代码				
代码	D			F	IVI					
MBJ01	8	18~4000	100000	M3~M8时	324 5	(C) LA()				
MBJ02	10	18~500	1-6-5-X0	M+2 SD < D	4 5 6	LA()				

MBJ02-D8-L150-E20-P5-M3-LC